BRUHAT BANGALORE MAHANAGARA PALIKE

Check list for the works pertaining to Yelahanka Zone

Sl No	Ward No	Name of Work	Est Amount Rs in Lakhs	Location details	Provision in the Estimate																			Remarks
					Asphalt work/Concrete work		Culverts				Side Drains			Shoulder Drain		Foot Path			Other works bldg/park, etc		Updation details			
					No. of Pot Hole	Avg Width in Mtrs	no	length in mtrs	RCC deck slab	other covering slabs i.e BS Slab etc	No	Nature(SSM/RCCL Shape/Box drain/Others)	Length in Kms No legnth	No	Length in Mtrs	nature slabs/concrete/graval etc.,	Length in Kms.	avg width in mtrs	Nature	Hiostory of the building /park etc	Road hisory	Property	Pre auditreport BBD/CBR etc	
1	*2*	*3*	*4*	*5*	*6*	*7*	*8*	*9*	*10*	*11*	*12*	*13*	*14*	*15*	*16*	*17*	*18*	*19*	*20*	*21*	*22*	*23*	*24*	*25*
1	6	Pot Hole Filling and Road patch work in Dasarahalli Surrounding Area in Ward No. 06 Byatarayanapura Sub Division	5.00	Dasarahalli main Road Cross	30																			
				Bhuvaneshawarinagara Main	40																			Pot Hole Fil
				Cross Roads	30																			Pot Hole Fil
				Cauvery Layotu	30																			Pot Hole Fil
				Mariyannapalaya	26																			Pot Hole Fil
				maruthi layout	23																			Pot Hole Fil

Assistant Engineer

Assistant Executive Engineer

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು-24

Executive Engineer

14/12

Chief Engineer